



Photo 1. View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is progressing on the fill slope.



Photo 2. View of the project area from the northeastern corner facing center.



Photo 3. View of a cobble run-down in the eastern portion of the project area.



Photo 4. View of a rock run-down in the northeastern corner of the project area.



Photo 5. View of the southern portion of the project area from the southeastern corner facing westward.



Photo 6. View of the western cut-slope from the southwestern corner of the well pad facing northward.



Photo 7. View of the southern portion of the well pad from the southeastern corner facing westward. If it is determined that this large area is not needed for production operations, than it should be reclaimed.