

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/21/2016

Submitted Date:

10/24/2016

Document Number:

682501434**FIELD INSPECTION FORM**
 Loc ID 442964 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____
Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 35080Name of Operator: GRAND MESA OPERATING COAddress: 1700 N. WATERFRONT PKWY BL 600City: WICHITA State: KS Zip: 67206**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|--------------------|---------|
| Brewer, Phyllis | (316) 265-3000 | pbrewer@gmocks.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 442963 | WELL | XX | 08/23/2015 | LO | 121-11053 | Buzzs Boat 14 | CI |

General Comment:

This is a pre-drill construction and stormwater inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location ConstructionLocation ID: 442964

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____ CDP: _____

Comment: _____

Corrective Action: _____ Date: _____

Form 2A COAs:**Comment:** _____Corrective Action: _____ **Date:** _____**Wildlife BMPs:****Comment:** _____Corrective Action: _____ **Date:** _____**Stormwater:**

| Erosion BMPs | Present | Other BMPs | Present |
|--------------|---------|------------|---------|
| BERMS | Yes | | |

Comments: Erosion BMPs: _____

Other BMPs: _____

Corrective Action: _____ Date: _____

SLOPE ROUGHENING

Yes

Comments: Erosion BMPs: Surface roughening

Other BMPs:

Corrective Action: _____ Date: _____

Comment: Surface roughening incorporated around entire perimeter of location, and parallel to the area of where the access road will be constructed. Berm constructed on the western and northern perimeter of the location and have been adequately tracked. Topography of the location slopes down to the northwest. Eastern portion of the location is relatively flat. BMPs implemented appear to be site specific and sufficient. Continue to maintain BMPs and adjust as needed.

**Corrective
Action:**

Date: _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 442963 Type: WELL API Number: 121-11053 Status: XX Insp. Status: CI

COGCC Comments

| Comment | User | Date |
|--|------------|------------|
| Ephemeral wetland (playa) feature to the NW of the location. | trujilloam | 10/24/2016 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 682501434 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3983007 |
| 682501435 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982959 |