



**photo 1:** Facing east along the access road near the Wriggly Red 44-21 location. This portion of pre-existing road had recently been seeded and hydromulched.



**photo 2:** Facing northeast along the access road near the Wriggly Red 44-21 location. This portion of pre-existing road had recently been seeded and hydromulched.



**photo 3:** Facing southeast along reclaimed access road which enters the canyon.



**photo 4:** Facing southwest toward along the access road near the Jumping Cow 42-28 location.



**photo 5:** Facing southwest toward the Jumping Cow 42-28 location.



**photo 6:** Facing south toward the location. The east side has been seeded and hydromulched.



**photo 7:** North side of the location facing southwest toward the cut slope.



**photo 8:** South side of the location facing west. Rip/rap rock has been placed in this area for stormwater control.



**photo 9:** South side of the location facing northeast.



**photo 10:** East side of the location facing north along the fill slope.