

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2016

Submitted Date:

10/25/2016

Document Number:

678300556**FIELD INSPECTION FORM**
 Loc ID _____ Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|--------------|--|-------------------------------------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | All Inspections |
| Evans, Jacob | 303-328-5605 | jacob.evans@nblenergy.com | Noble Environmental |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|---------------------|--------|-------------|------------|---------|---------------------|-------------|
| 444944 | SPILL OR RELEASE | AC | 02/29/2016 | | - | SPILL/RELEASE POINT | EI |

General Comment:

Tank battery at site has been removed. Form 27 required by rule for closure of partly buried produced water vessel at site as described in spill report. Submit form 27 as part of spill closure process in 45 days or less (9 Dec 2016)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|----------|-------------|---|---------|----|---------------|----|
| Facility ID: | 444944 | Type: | SPILL OR | API Number: | - | Status: | AC | Insp. Status: | EI |

| |
|--|
| |
|--|

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____
Comment: [spill 444944](#)
Corrective Action: [Submit form 27 as part of spill closure process iin 45 days or less \(9 Dec 2016\)](#) Date: 12/09/2016
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [spill 444944 not closed and more than 6 months since incident.](#)

Corrective Action:

Date: 12/09/2016

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 678300556 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3983687 |