


# Stormwater Inspection



**Photo 1.** Photo taken from northwest corner of perimeter, facing East. Stabilized sediment trap installed. Topsoil pile stored along western location.



# Stormwater Inspection



**Photo 2.** Photo taken from northwest corner of perimeter, facing South. Ditch and berm constructed around outer perimeter of the location.



## Stormwater Inspection



**Photo 3.** Photo taken from southwest corner of perimeter, facing East. Ditch and berm constructed around outer perimeter of the location.



# Stormwater Inspection



**Photo 4.** Photo taken from southeast corner of perimeter, facing North. Ditch and berm constructed around outer perimeter of the location.



# Stormwater Inspection



**Photo 5.** Photo taken from northeast corner of perimeter, facing West. Stabilized sediment trap installed.



## Stormwater Inspection



**Photo 6.** Photo taken from northeast corner of perimeter, facing West. Ditch and berm constructed around outer perimeter of the location.