

Stormwater Inspection

Topsoil pile



Photo 1. Photo taken from northwestern corner of perimeter, facing South, south of the access road. Stabilized sediment trap installed. Topsoil pile stored along western location. Ditch and berm constructed around outer perimeter of the location.

Stormwater Inspection



Photo 2. Photo taken from northwest corner of perimeter, facing East, north of the access road. Stabilized sediment trap installed. Ditch and berm constructed around outer perimeter of the location.

Stormwater Inspection



Photo 3. Photo taken from southern perimeter of the location, facing West. Ditch and berm constructed around outer perimeter of the location.

Stormwater Inspection



Photo 4. Photo taken from southern perimeter of the location, facing East. Ditch and berm constructed around outer perimeter of the location.

Stormwater Inspection



Photo 5. Photo taken from eastern perimeter of the location, facing South. Ditch and berm constructed around outer perimeter of the location.

Stormwater Inspection



Photo 6. Photo taken from eastern perimeter of the location, facing North. Ditch and berm constructed around outer perimeter of the location.