

## Federal 4-35

Inspection# 673403813

No capacity on tank label.  
Low berm with dried annual  
weeds adjacent to tank.



Erosion rills on access road.  
Hard hat for scale.



Standing in the drainage  
looking uphill at rill in  
previous picture.



Sediment entering drainage  
from access road.

