

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/01/2016
Submitted Date:
11/01/2016
Document Number:
672500109

FIELD INSPECTION FORM

Loc ID 333130 Inspector Name: Gomez, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 370 17TH STREET #2170
City: DENVER State: CO Zip: 80202

Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------------------|---------|
| | | cogcc.inspections@crestonepr.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 275792 | WELL | PR | 11/05/2005 | GW | 123-22675 | OSKARSON 23-33 | PR |

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---------------|-------|--|
| | Type WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|---------------|-------|--|
| | Type WELLHEAD | | |
| Comment: | AG PANEL | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | | | |
|--------------------|-----|-------|--|--|-----------------|
| | | | | | corrective date |
| Type: Plunger Lift | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tanak ID | SE GPS |
|--------------------|---|----------|---------------------|----------|--------|
| | | | CENTRALIZED BATTERY | | , |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 275792 Type: WELL API Number: 123-22675 Status: PR Insp. Status: PR

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------|---|
| 672500110 | Thermal Image | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3990535 |