



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type	Area	Volume			corrective date
Type: Gas Meter Run		# 2			
Comment:					
Corrective Action:				Date:	
Type: Progressive Cavity		# 2			
Comment:					
Corrective Action:				Date:	
Type: Deadman # & Marked		# 5			
Comment:	3 marked, 2 unmarked.				
Corrective Action:				Date:	11/26/2016
Type: Compressor		# 1			
Comment:					
Corrective Action:				Date:	
Type: Vertical Separator		# 2			
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 273552 Type: WELL API Number: 071-08192 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

Facility ID: 285807 Type: WELL API Number: 071-08872 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: c

**Fencing:**

Fencing Type: Livestock      Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date:

Anchor Trench Present: \_\_\_\_\_      Oil Accumulation: NO      2+ feet Freeboard:

Comment: 30' x 60'

Corrective Action

Date:

Monitoring:	Monitoring Type	Comment`
	Chain	

**COGCC Comments**

Comment	User	Date
<a href="#">SEE : Equipment : deadman.</a>	duranj	10/26/2016

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
668004890	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3984890">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3984890</a>