

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2016

Submitted Date:

10/26/2016

Document Number:

678300570**FIELD INSPECTION FORM**
 Loc ID 327368 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10311Name of Operator: SYNERGY RESOURCES CORPORATIONAddress: 20203 HIGHWAY 60City: PLATTEVILLE State: CO Zip: 80651**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pennington, David		dpennington@syrginfo.com	<a href="#">All Synergy Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246776	WELL	PR	03/01/2015	GW	123-14573	WOLFSON 26-1	EI
446347	TANK BATTERY	AC	06/27/2016		-	WOFLSON-64N67W 26NENE	EI

**General Comment:**

well has been plugged and battery removed. Remediation 9796 approved with COA for PBV water vesel removal.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	TRASH		
Comment:	trash including wood and plastic sheeting at site		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 11/07/2016

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:	shed and meter on location and apparently not needed as well plugged		
Corrective Action:	remove as part of interim and final reclamation or show why needed		Date: 04/26/2017

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>246776</u>	Type:	<u>WELL</u>	API Number:	<u>123-14573</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>446347</u>	Type:	<u>TANK</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678300570	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3984980">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3984980</a>
678300571	shed	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3984951">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3984951</a>
678300572	trash	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3984952">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3984952</a>