

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/19/2016

Submitted Date:

10/28/2016

Document Number:

680601013

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
307014 \_\_\_\_\_ ROY, CATHERINE \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 26580  
 Name of Operator: BURLINGTON RESOURCES OIL & GAS LP  
 Address: PO BOX 4289  
 City: FARMINGTON State: NM Zip: 87499

**Findings:**

- 7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Walker, Crystal		Crystal.Walker@conocophillips.com	All Inspections
Busse, Dollie	505-324-6104	Dollie.L.Busse@conocophillips.com	All SW Inspections
Notor, Lori		Lori.R.Notor@conocophillips.com	SW Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295743	WELL	PR	03/13/2009	GW	067-09551	ALLISON UNIT 116T (LOWER HOL	RI

**General Comment:**

This is a followup inspection to inspection number 680600277 conducted on October 20, 2015.

**Inspected Facilities**

Facility ID: 295743 Type: WELL API Number: 067-09551 Status: PR Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Project area is surrounded by grazed pasture.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment Russian thistle debris identified in previous inspection was not observed.

Corrective Action  Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action  Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_



**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Stormwater erosion is controlled on the location at this time.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680601013	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3987687">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3987687</a>
680601014	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3987632">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3987632</a>