



Photo 1. View of the southern portion of the project area from the southeastern corner facing center toward the well.



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward.



Photo 3. View of cement debris that needs to be removed in the eastern portion of the project area.



Photo 4. View of the northern portion of the project area from the northeastern edge facing westward. Musk thistles (*Carduus nutans*) from the 2016 growing season grew to maturity and are senescing.



Photo 5. View of musk thistle rosettes in the eastern portion of the project area.



Photo 6. View of stormwater erosion and sediment deposition into a drainage in the northeastern corner of the project area.