

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/28/2016

Submitted Date:

10/31/2016

Document Number:

674602920**FIELD INSPECTION FORM**
 Loc ID 423033 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10439Name of Operator: CARRIZO NIOBRARA LLCAddress: 500 DALLAS STREET #2300City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hazard, Ellice		ellice.hazard@state.co.us	
Lowery, Sheldon	713-358-6492	sheldon.lowery@crzo.net	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Johansson, Eric	713-358-6227	eric.johansson@crzo.net	
Schneider, Jeff	970-867-9437/ (214) 244-3819	jeff@schneiderenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423029	WELL	PR	10/13/2011	OW	087-08161	Wickstrom 5-44-5-60	EG

General Comment:

COGCC Integrity Inspector met with Carrizo Oil and Gas Production Foreman Bryce Jess (along with contract personnel) and witnessed annual pressure testing conducted on the flowlines associated with this well. Details in the flowline section of this report.

Inspected FacilitiesFacility ID: 423029 Type: WELL API Number: 087-08161 Status: PR Insp. Status: EG**Flowline**

#1	Type:	4 of Lines
----	-------	------------

Flowline Description

Flowline Type: Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Yes Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Pressure testing witnessed on the following: Well site (wellhead to separator), oil dump, produced water dump and gas sales flowlines. All tests witnessed are deemed passing/satisfactory. (4) individual flowline pressure tests were completed. Note: The well site flowline was hydrotested / data logger (Crystal Gauge) used to record each pressure test - records retained by Carrizo.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674602920	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3988921