

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/24/2016

Submitted Date:

10/31/2016

Document Number:

674901362

FIELD INSPECTION FORM

Loc ID 385898 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
 Name of Operator: BP AMERICA PRODUCTION COMPANY
 Address: 380 AIRPORT RD
 City: DURANGO State: CO Zip: 81303

Findings:

- 8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Kubeczko, Dave		dave.kubeczko@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Brown, Walt	970-385-1372	wabrown@fs.fed.us	
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261128	WELL	PR	09/13/2013	GW	067-08520	YANKEE FEDERAL A 2	EI

General Comment:

On October 24, 2016 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Yankee Federal A #2. For the most recent field inspection report of this facility, please refer to document #685300482. The purpose of this site visit was an onsite meeting between the operator and the Forest Service regarding future work on the San Juan National Forest.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	Stock panel fencing around well head and pump jack. Guard fencing around pump jack.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Stock panel fencing around separator, meter run, and produced water PBV.		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.274965,-107.511095
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)	95 bbl.				
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 261128 Type: WELL API Number: 067-08520 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Compaction	Pass	Compaction	Pass			
Berms	Pass	Gravel	Pass			
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On October 24, 2016 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Yankee Federal A #2. For the most recent field inspection report of this facility, please refer to document #685300482. The purpose of this site visit was an onsite meeting between the operator and the Forest Service regarding future work on the San Juan National Forest.	hughesj	10/31/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901362	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3988973
674901363	Yankee Federal A #2 production equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3988958
674901364	Yankee Federal A #2 pump jack.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3988959