

**FORM  
INSP**Rev  
X/15

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/31/2016

Submitted Date:

11/01/2016

Document Number:

666802689**FIELD INSPECTION FORM**

Loc ID 334604 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257351	WELL	PR	06/19/2005	GW	045-07538	GMR 33-16 (P33NW)	PR
257352	WELL	PR	06/01/2002	GW	045-07539	GMR 34-13 (P33NW)	PR
257353	WELL	PR	10/29/2000	GW	045-07540	GMR 3-12 (P33NW)	PR
257354	WELL	PR	12/17/2000	GW	045-07541	GMR 4-9 (P33NW)	PR

**General Comment:**[Shared facilities with location ID 334587](#)

**Location**Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-0552-001		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	Blow down muffler		
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
METHANOL	2	1000 GAL	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:		Date:			

**Paint**

Condition	
Other (Content)	

Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE	4	300 BBLs	STEEL AST		39.477022,-107.772173	
Comment:						
Corrective Action:				Date:		
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:				Date:		
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:				Date:		

Inspected Facilities				
Facility ID: 257351	Type: WELL	API Number: 045-07538	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:			Date:	
Facility ID: 257352	Type: WELL	API Number: 045-07539	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:			Date:	
Facility ID: 257353	Type: WELL	API Number: 045-07540	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:			Date:	
Facility ID: 257354	Type: WELL	API Number: 045-07541	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:			Date:	

## Environmental

### Spill/Remediation:

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Culverts	Pass			
Ditches	Pass					
Seeding	Pass					
Gravel	Pass					
		Ditches	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666802689	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3990519">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3990519</a>