

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2016

Submitted Date:

11/01/2016

Document Number:

682401425**FIELD INSPECTION FORM**

Loc ID 444427 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Brebis, Chad		COGCCinspections@anadarko.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444424	WELL	XX	12/23/2015	LO	123-42622	JAGUAR 14N-35HZ	RI
444425	WELL	XX	12/23/2015	LO	123-42623	JAGUAR FED 35N-35HZ	RI
444426	WELL	XX	12/23/2015	LO	123-42624	JAGUAR 36C-35HZ	RI
444428	WELL	XX	12/23/2015	LO	123-42625	JAGUAR 3N-14HZ	RI
444429	WELL	XX	12/23/2015	LO	123-42626	JAGUAR 3C-14HZ	RI
444430	WELL	XX	12/23/2015	LO	123-42627	JAGUAR FED 29N-14HZ	RI
444431	WELL	XX	12/23/2015	LO	123-42628	JAGUAR 28C-14HZ	RI
444432	WELL	XX	12/23/2015	LO	123-42629	JAGUAR FED 35C-35HZ	RI
444433	WELL	XX	12/23/2015	LO	123-42630	JAGUAR FED 6S-35HZ	RI

**General Comment:**

This is a stormwater inspection in response to Form 42 Document #401117770 on a recent construction build.

**Location Construction**

Location ID: 444427

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: SATISFACTORY CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

Inspected Facilities				
Facility ID: <u>444424</u>	Type: <u>WELL</u>	API Number: <u>123-42622</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444425</u>	Type: <u>WELL</u>	API Number: <u>123-42623</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444426</u>	Type: <u>WELL</u>	API Number: <u>123-42624</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444428</u>	Type: <u>WELL</u>	API Number: <u>123-42625</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444429</u>	Type: <u>WELL</u>	API Number: <u>123-42626</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444430</u>	Type: <u>WELL</u>	API Number: <u>123-42627</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444431</u>	Type: <u>WELL</u>	API Number: <u>123-42628</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444432</u>	Type: <u>WELL</u>	API Number: <u>123-42629</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>444433</u>	Type: <u>WELL</u>	API Number: <u>123-42630</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Sediment Traps	Pass					
Berms	Pass					

Comment: Ditch and berm BMP installed around the perimeter of the location, and two (2) stabilized sediment traps installed in the northwestern perimeter of the location. Refer to attached photos in Document #682401426.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401425	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3989719">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3989719</a>
682401426	Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3989408">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3989408</a>