

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
10/28/2016  
Submitted Date:  
11/02/2016  
Document Number:  
685301675

**FIELD INSPECTION FORM**

Loc ID 325420 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 5852  
Name of Operator: BAIRD\* JERRY  
Address: 989 HIGHWAY 140  
City: HESPERUS State: CO Zip: 81326

**Findings:**

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214744	WELL	DM	09/29/1999	GW	067-06348	TALLEY 1	DM

**General Comment:**

Inspection report contains corrective action and comment. See Signs/Marker Equipment section of report for additional details. See link at end of report for path to downloadable pictures.

*(This area is currently blank for additional comments.)*

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	No sign at wellhead.		
Corrective Action:	Install sign to comply with Rule 210.b		Date: 01/06/2017
Emergency Contact Number:			
Comment:	No sign with emergency contact posted.		
Corrective Action:	Install sign to comply with Rule 210.b		Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Flow Line	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Domestic Tap Equipment		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead. At time of inspection wellhead was venting gas at nipple connection. Well owner notified.		
Corrective Action:	Repair or replace connection and securely fasten all valves, pipes, and fittings to comply with Rule 605.d		Date: 12/02/2016
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 214744 Type: WELL API Number: 067-06348 Status: DM Insp. Status: DM

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685301675	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3991156">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3991156</a>
685301704	Wellhead and Domestic Tap	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3991095">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3991095</a>
685301705	Leaking wellhead joint	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3991096">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3991096</a>