



Photo#1:

View North over Location Center



Photo#2:

View South over Location Center



November 8, 2016

Inspection Photos: Gulfport Energy DA Juniper4-3 API#081-07587


Photo#3:

View East over Location Center




Photo#4:

View West over Location Center



Photo#5:
Entry into Location



Photo#6:
View NE along Access Road into Location




November 8, 2016

Inspection Photos: Gulfport Energy DA Juniper4-3 API#081-07587


Photo#7:

Gravel not Removed from Access Road.



Photo#8:

Noxious Weeds establishing on un-reclaimed Access Road





Photo#9: View up Access Road exiting Location to West.

November 8, 2016

Inspection Photos: Gulfport Energy DA Juniper4-3 API#081-07587