

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
11/10/2016  
Submitted Date:  
11/15/2016  
Document Number:  
672500163

**FIELD INSPECTION FORM**

Loc ID 323314 Inspector Name: Gomez, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1625 BROADWAY STE 2200  
City: DENVER State: CO Zip: 80202

**Findings:**

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245056	WELL	PR	04/27/1999	OW	123-12851	ANDERSON-COOMBS 5	PA

**General Comment:**

*(This area is intentionally left blank for general comments.)*

**Inspected Facilities**

Facility ID: 245056 Type: WELL API Number: 123-12851 Status: PR Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: BWS

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Cement Type: \_\_\_\_\_

Comment: tagged at 110' this morning. So here is results from today thanks. We also pumped 280 57 bbls 15.8 ppg g-neat cement slurry yesterday instead of 250 sks.

TOP OFF WELL. TAG CEMENT @ 110' PUMP 37 SKS 7.5 BBLS 15.8 PPG G-NEAT CEMENT SLURRY FROM 110'-SUR. WASH UP TRUCKS BACK AT BAYOU 10. SECURE WELL. SDFN.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_