

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2016

Submitted Date:

11/08/2016

Document Number:

666802718**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 335141 \_\_\_\_\_ Murray, Richard \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	<a href="#">Field Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272786	WELL	PR	06/04/2004	GW	045-10160	WILLIAMS RMW 148-29	PR
272787	WELL	PR	12/03/2004	GW	045-10159	WILLIAMS RWF 12-29	PR
272790	WELL	PR	01/02/2006	GW	045-10156	WILLIAMS RWF 41-30	PR
286770	WELL	PR	09/15/2006	GW	045-12722	WILLIAMS RWF 11-29	PR
286771	WELL	PR	09/15/2006	GW	045-12721	WILLIAMS RWF 311-29	PR
286772	WELL	PR	09/15/2006	GW	045-12720	WILLIAMS RWF 411-29	PR

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-1177-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 6		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:			Date:		
Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		39.501646,-107.917325

Comment:		
Corrective Action:		Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	272786	Type:	WELL	API Number: 045-10160	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	272787	Type:	WELL	API Number: 045-10159	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	272790	Type:	WELL	API Number: 045-10156	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	286770	Type:	WELL	API Number: 045-12722	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	286771	Type:	WELL	API Number: 045-12721	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	286772	Type:	WELL	API Number: 045-12720	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
		Gravel	Pass			
Slope Roughening	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666802718	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3998247">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3998247</a>