

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2016

Submitted Date:

11/08/2016

Document Number:

685301772**FIELD INSPECTION FORM**
 Loc ID 312063 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|---------------------------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | COGCC |
| Beebe, Sabre | 970-375-7530 | Sabre.Beebe@bp.com | SW Inspection Reports |
| Inspections, All | | SanJuanCOGCC@bp.com | SW Inspection Reports |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 259759 | WELL | PR | 03/15/2002 | GW | 067-08423 | HUNGERFORD A 2 | PR |
| 298810 | WELL | PR | 07/11/2010 | GW | 067-09633 | HUNGERFORD A 4 | PR |

General Comment:

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☐

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|----------------------|----------------------|--|
| Emergency Contact Number: | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | |
| | Date: | <input type="text"/> | |

Overall Good: ☐

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------------------------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |
| Type | PUMP JACK | | |
| Comment: | Steel Mesh Safety Barrier | | |
| Corrective Action: | | Date: | |
| Type | PUMP JACK | | |
| Comment: | 6' Chain Link Fence Barrier | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Panel - Includes Produced Water Tank | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Electrical Service Equipment | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|---|-------|--|
| Type: Ancillary equipment | # 1 | | |
| Comment: | Telemetry Equipment | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 2 | | |
| Comment: | Double | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Chemical Tank and Pump with Spill Prevention. | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 2 | | |
| Comment: | Electric Motor | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 2 | | |
| Comment: | Wellhead | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tanak ID | SE GPS |
|--------------------|----------------------------------|----------|-----------|----------|--------|
| PRODUCED WATER | 1 | OTHER | PBV STEEL | | , |
| Comment: | Double walled tank with a stack. | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | 95 BBLS |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 259759 | Type: | WELL | API Number: | 067-08423 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 298810 | Type: | WELL | API Number: | 067-09633 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: W side of location has landowner storage along graveled edge of location.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | Material Handling And Spill Prevention | Pass | |
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 685301772 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3998080 |