

**Foundation Energy Management LLC  
Federal 12-3 Second Follow up  
Inspection Doc#675203618**

Vegetaion/ Vegetation  
debris in tank containment.



Vegetation/ vegetation  
debris in pit





Erosion across roadway



Traffic driving around area of erosion in access road



Open top tank near capacity

