

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/16/2016
Submitted Date:
11/16/2016
Document Number:
685501338

FIELD INSPECTION FORM

Loc ID 319729 Inspector Name: MONTOYA, JOHN On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
14 Number of Comments
5 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 74165
 Name of Operator: RENEGADE OIL & GAS COMPANY LLC
 Address: 6155 S MAIN STREET #210
 City: AURORA State: CO Zip: 80016

Contact Information:

Contact Name	Phone	Email	Comment
Espinosa, Bill		billespinosa30@yahoo.com	Inspections
Condill, J.B.		jbcrog@aol.com	
Ingve, Ed	303-829-2354	ed@renegadeoilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201161	WELL	PR	08/22/1995	OW	001-06564	BRUCHEZ 1	PR

General Comment:

Location			
Lease Road:			
Type	Main		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	OK		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	soiled dirt around motor mounts no bandaids please dig the soiled dirt out		
Corrective Action:	"Comply with Rule 603.f using the Rule 603.f guidance document for further details. "		Date: <u>12/15/2016</u>
Crude Oil	Treater	<= 1 bbl	
Comment:	SOILED DIRT INSIDE TREATER HOUSE		
Corrective Action:	"Comply with Rule 603.f using the Rule 603.f guidance document for further details. "		Date: <u>12/15/2016</u>
Crude Oil	Tank	<= 1 bbl	
Comment:	SOILED DIRT AT DRAIN LINE ON OIL PROD TANK		
Corrective Action:	"Comply with Rule 603.f using the Rule 603.f guidance document for further details. "		Date: <u>12/15/2016</u>
In Containment: Yes _____			
Comment:	SOILED DIRT INSIDE TREATER HOUSE		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	BARBWIRE FENCE		
Corrective Action:			Date:

Type	TANK BATTERY		
Comment:	BARBWIRE FENCE		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Barbwire fence se corner n39.87416 w-104.26974		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Veritcal Heater Treater	# 1		
Comment:	se corner n39.87387 w-104.26885		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	ser c orner n39.87387 w-104.26885		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.873510,-104.268790
Comment:					
Corrective Action:					Date:

Paint	
Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	berms in dis-repair will not hold capacity of largest tank			

Corrective Action:	"Location is within a designated setback location, repair or install berms or other secondary containment devices per Rule 604.c.(2)G."	Date:	12/15/2016
--------------------	---	-------	------------

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,

Comment:	
Corrective Action:	
Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	berms in dis-repair			
Corrective Action:	"Location is within a designated setback location, repair or install berms or other secondary containment devices per Rule 604.c.(2)G."			Date: 12/15/2016

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities

Facility ID: 201161 Type: WELL API Number: 001-06564 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING Pass

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION Pass

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS Pass

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION Pass

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____ Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
TRANSECT RESULTS OF DISTURBED AREA% _____
TRANSECT RESULTS OF REFERENCE AREA% _____
TOTAL % OF DESIRABLE VEGETATION COVER _____
VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
TRANSECT RESULTS OF DISTURBED AREA% _____
TRANSECT RESULTS OF REFERENCE AREA% _____
TOTAL % OF DESIRABLE VEGETATION COVER _____
VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input type="text"/> Corrective Action: <input type="text"/>						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
	montoyaj	11/16/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685501339	GEAR BOX LEAK	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004927
685501340	GEAR BOX NEEDS REPAIRED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004928
685501341	GEAR BOX	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004929
685501342	SOILED DIRT MOTOR MOUNTS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004930
685501343	BANDAID ON SOILED DIRT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004931
685501344	WELL SIGN	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004932
685501345	SOILED DIRT IN FRONT DOOR TREATER HOUSE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004933
685501346	SOILED DIRT INSIDE TREATER HOUSE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004934
685501347	BADAID ON SOILED DIRT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004935
685501348	SOILED DIRT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004936
685501349	SOILED DIRT AT METER RUN	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004937
685501350	2' VALVE LEAKING	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004938
685501351	NEED CAPS ON LINES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004939
685501352	BERMS WILL NO HOLD CAPACITY OIF LAERGEST TANK	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004940
685501353	BATTERY SIGN	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4004941