

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/10/2016

Submitted Date:

11/10/2016

Document Number:

666802726

FIELD INSPECTION FORM

Loc ID 335102 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
 Name of Operator: ENCANA OIL & GAS (USA) INC
 Address: 370 17TH ST STE 1700
 City: DENVER State: CO Zip: 80202-

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272024	WELL	PR	12/01/2004	GW	045-09998	GMR 34-3 (B34NW)	PR
272025	WELL	PR	11/23/2004	GW	045-09999	GMR 34-2 (B34NW)	PR
272026	WELL	PR	12/27/2004	GW	045-10000	GMR 34-1B (B34NW)	PR
272027	WELL	PR	11/29/2004	GW	045-10001	GMR 34-2B (B34NW)	PR

General Comment:

[shared facilities with location ID 335095.](#)

Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tanak ID	SE GPS		
OTHER	1	OTHER	PLASTIC AST		,		
Comment:		chemical unit, centralized battery					
Corrective Action:				Date:			
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tanak ID	SE GPS		
CONDENSATE	4	500 BBLs	STEEL AST		39.487532,-107.760875		
Comment:							
Corrective Action:				Date:			
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:				Date:			
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:				Date:			
Flaring:							
Type							
Comment:							
Corrective Action:				Date:			

Inspected Facilities									
Facility ID:	<u>272024</u>	Type:	<u>WELL</u>	API Number:	<u>045-09998</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>272025</u>	Type:	<u>WELL</u>	API Number:	<u>045-09999</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>272026</u>	Type:	<u>WELL</u>	API Number:	<u>045-10000</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>272027</u>	Type:	<u>WELL</u>	API Number:	<u>045-10001</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Berms	Pass					
Seeding	Pass					
Gravel	Pass					
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666802726	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005030