

Interim Reclamation Inspection



Photo 1. Photo taken from southwest location, facing North. Interim reclamation IN-PROCESS.

Interim Reclamation Inspection



Photo 2. Photo taken from southwest location, facing East. Interim reclamation IN-PROCESS.