



**photo 1:** Facing northeast toward the location which has been recontoured.



**photo 2:** West side of the location facing east.



**photo 3:** North side of the location which was being hydro-mulched.



**photo 4:** West side of the location facing southeast.



**photo 5:** East side of the location facing west.



**photo 6:** East side of the location facing north.