



photo 1: Facing west along the access road.



photo 2: Facing west along the access road.



photo 3: Facing west along the access road.



photo 4: Facing back to the east along the access road. There are signs of erosion occurring.



photo 5: The rock check dams are not maintained and erosion is occurring along the road side.



photo 6: The rock check dams are not maintained and erosion is occurring along the road side.



photo 7: Rock rip/rap has been placed at the north side of the location.



photo 8: Facing west along the access road.



photo 9: Facing west toward the location.



photo 10: East side of the location facing west toward the rocky fill slope.



photo 11: West side of the location facing east toward the rocky fill slope.



photo 12: East side of the location facing northeast.



photo 13: East side of the location facing north toward the cut slope.



photo 14: Facing toward the rock cut slope at the northwest side of the location.



photo 15: West side of the location facing east.



photo 16: East side of the location facing west.