



**photo 1:** Facing west along the access road.



**photo 2:** Facing west along the access road.



**photo 3:** The cut slope of the access road does not have much vegetation establishment for stabilization.



**photo 4:** Facing north toward the location along the access road.



**photo 5:** Facing north toward the location.



**photo 6:** Facing north along the west fill slope of the location.



**photo 7:** Facing south toward the location.



**photo 8:** Facing east toward the cut slope side of the location.



**photo 9:** Facing south toward the location.



**photo 10:** The vegetation along areas of the cut slope does not appear to be adequately established.