

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
11/14/2016  
Submitted Date:  
11/14/2016  
Document Number:  
684902600

**FIELD INSPECTION FORM**

Loc ID 318405 Inspector Name: Pesicka, Conor On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: K P KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

| Contact Name      | Phone        | Email         | Comment                         |
|-------------------|--------------|---------------|---------------------------------|
| Lara-Mesa, Susana | 303-825-4822 | cogcc@kpk.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 241237      | WELL | PR     | 12/13/1976  | OW         | 123-09025 | DITLEV-SIMONSEN C 3 | PR          |

**General Comment:**

*(This area is intentionally left blank for general comments.)*

**Location**

Overall Good:

**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  | Date: |  |
| Corrective Action: |  |       |  |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |                                    |       |  |
|--------------------|------------------------------------|-------|--|
| Type               | PUMP JACK                          |       |  |
| Comment:           | chain link topped with barbed wire |       |  |
| Corrective Action: |                                    | Date: |  |

**Equipment:**

|                    |          |       |                 |
|--------------------|----------|-------|-----------------|
| Type: Prime Mover  | # 1      |       | corrective date |
| Comment:           | electric |       |                 |
| Corrective Action: |          | Date: |                 |
| Type: Pump Jack    | # 1      |       |                 |
| Comment:           |          |       |                 |
| Corrective Action: |          | Date: |                 |

**Tanks and Berms:**

| Contents           | #                                       | Capacity | Type                | Tanak ID | SE GPS                |
|--------------------|---|----------|---------------------|----------|-----------------------|
|                    |   |          | CENTRALIZED BATTERY |          | 40.098820,-104.959570 |
| Comment:           | Spindle Consolidation Facility Number 4 |          |                     |          |                       |
| Corrective Action: |   |          |                     | Date:    |                       |

**Paint**

|                  |                      |
|------------------|----------------------|
| Condition        | <input type="text"/> |
| Other (Content)  | <input type="text"/> |
| Other (Capacity) | <input type="text"/> |
| Other (Type)     | <input type="text"/> |

**Berms**

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|      |          |                     |                     |             |

|                    |  |       |
|--------------------|--|-------|
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 241237 Type: WELL API Number: 123-09025 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Comment: Bradenhead plumbed to surface.

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 684902600    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4002444">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4002444</a> |