



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:		Date:	
Type	PIT		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Progressive Cavity	# 2		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	
Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 268075 Type: WELL API Number: 071-07864 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

Facility ID: 280492 Type: WELL API Number: 071-08560 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: \_\_\_\_\_ Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: c

**Fencing:**

Fencing Type: Livestock Fencing Condition: Adequate

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: NO 2+ feet Freeboard: \_\_\_\_\_

Comment: 30' x 60'

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

Type: Produced Water Lined: NO Pit ID: \_\_\_\_\_ Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: c

**Fencing:**

Fencing Type: Livestock Fencing Condition: Adequate

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:			Date:
Corrective Action			
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard:	
Comment:	20' x 40'		Date:
Corrective Action			
Monitoring:	Monitoring Type	Comment`	
	Chain		
	Chain		

**COGCC Comments**

Comment	User	Date
<a href="#">Bullet hole in Solar Panel for Kraft 23-17R.</a>	duranj	11/15/2016

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
668004945	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4003722">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4003722</a>