

Corrective Action:

Date:

Inspected Facilities

Facility ID: 273270 Type: WELL API Number: 071-08156 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 286818 Type: WELL API Number: 071-08990 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____

Comment: 50' x 60'

Corrective Action

Date: _____

Monitoring:

Monitoring Type	Comment
Chain	

COGCC Comments

Comment	User	Date
SEE : Signs/Marker : Wrong APi # on the Anderson 43-18V.	duranj	11/09/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
668004951	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4008494