

# Construction and Stormwater Inspection



**Photo 1.** Photo taken from the southern location , facing East. Ditch and berm BMP installed around the location perimeter.

# Construction and Stormwater Inspection



**Photo 2.** Photo taken from the southeastern location, facing West, towards the sediment trap. Sediment trap side slopes should not be steeper than 2:1 and the outlet should be stabilized (e.g., geotextile with rip rap on top).

# Construction and Stormwater Inspection



**Photo 3.** Photo taken from the eastern location, facing West, towards the topsoil stockpile. Topsoil needs to be stabilized and protected from degradation due to wind and water erosion.

# Construction and Stormwater Inspection



**Photo 4.** Photo taken from the northeastern location, facing West, towards the sediment trap. Sediment trap side slopes should not be steeper than 2:1 and the outlet should be stabilized (e.g., geotextile with rip rap on top). May need to consider where to locate sediment trap in the future because the topsoil stockpile material is almost coming over the west-berm of the sediment trap.

# Construction and Stormwater Inspection



**Photo 5.** Photo taken from the northeast location , facing West. Ditch and berm BMP installed around the location perimeter. Ditch should be constructed with a 2:1 slope on both sides.

# Construction and Stormwater Inspection



**Photo 6.** Photo taken from the northwest location , facing South. Ditch and berm BMP installed around the location perimeter. Ditch should be constructed with a 2:1 slope on both sides.