

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2016

Submitted Date:

11/18/2016

Document Number:

673403861**FIELD INSPECTION FORM**

Loc ID 430051 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10525Name of Operator: SANTA FE NATURAL RESOURCES INCAddress: 4833 FRONT STREET UNIT B 506City: CASTLE ROCK State: CO Zip: 80104**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------|----------------|-------------------------|---------|
| SULLIVAN, MICHAEL | (303) 681-5901 | durangopl@earthlink.net | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 430052 | WELL | PR | 09/05/2013 | OW | 081-07747 | Ridgeview 32-16-1 | SI |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|--|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Sign at wellhead still has previous operator. Santa Fe Resources has 60 days from purchase recorded by document number 401018574 on 4/29/2016 to update all signs on location. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: | 06/29/2016 |
| Type | BATTERY | | |
| Comment: | Sign at battery still has previous operator. Santa Fe Resources has 60 days from purchase recorded by document number 401018574 on 4/29/2016 to update all signs on location. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: | 06/29/2016 |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Tank labels still have previous operator. Santa Fe Resources has 60 days from purchase recorded by document number 401018574 on 4/29/2016 to update all signs on location. | | |
| Corrective Action: | Install sign to comply with Rule 210.d. | Date: | 06/29/2016 |

Emergency Contact Number:

Comment: Signs on location still have previous operator. Santa Fe Resources has 60 days from purchase recorded by document number 401018574 on 4/29/2016 to update all signs on location.
No emergency contact information for Sante Fe Resources on location.

Corrective Action: Install sign to comply with Rule 210.

Date: 06/29/2016

Good Housekeeping:

| | | | |
|--------------------|--------------------------|-------|--|
| Type | WEEDS | | |
| Comment: | Dried weeds on location. | | |
| Corrective Action: | | Date: | |

Overall Good: ☐**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-----------|-------|--|
| Type | PIT | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | PUMP JACK | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------|-----|--|-----------------|
| Type: Pump Jack | # 1 | | corrective date |
| Comment: | | | |

| | | | |
|---------------------------------|-----|-------|--|
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Flare | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tanak ID | SE GPS |
|--------------------|---|----------|-----------|----------|-----------------------|
| PRODUCED WATER | 1 | 400 BBLs | STEEL AST | | 40.476100,-107.610960 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | | | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tanak ID | SE GPS |
|--------------------|---|----------|-----------|----------|--------|
| CRUDE OIL | 2 | 400 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | | | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|-----|-------|
| Type | Pit | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|--|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 430052 | Type: | WELL | API Number: | 081-07747 | Status: | PR | Insp. Status: | SI |
| Idle Well | | | | | | | | | |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____ | | | | | | | | | |
| Comment: _____ | | | | | | | | | |
| Corrective Action: _____ Date: _____ | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| | | | | | | |

Comment:

Corrective Action: Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| Follow up to inspection from 6/14/2016 document number 673403258. No corrective actions have been made. | waldrone | 11/18/2016 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 673403861 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007056 |
| 673403862 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007001 |