

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
11/18/2016  
Submitted Date:  
11/18/2016  
Document Number:  
685501392

**FIELD INSPECTION FORM**

Loc ID 320177 Inspector Name: MONTOYA, JOHN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
OGCC Operator Number: 74165  
Name of Operator: RENEGADE OIL & GAS COMPANY LLC  
Address: 6155 S MAIN STREET #210  
City: AURORA State: CO Zip: 80016

**Findings:**  
9 Number of Comments  
3 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

| Contact Name   | Phone        | Email                    | Comment                         |
|----------------|--------------|--------------------------|---------------------------------|
| Espinosa, Bill |              | billespinosa30@yahoo.com | <a href="#">Inspections</a>     |
| Ingve, Ed      | 303-829-2354 | ed@renegadeoilandgas.com | <a href="#">All Inspections</a> |
| Condill, J.B.  |              | jbcrog@aol.com           |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 202912      | WELL | PR     | 09/07/1994  | OW         | 001-08317 | WALKER ANN 2  | PR          |

**General Comment:**

| Location   |   |          |                         |
|--|---|----------|-------------------------|
| <b>Lease Road:</b>                                     |   |          |                         |
| Type   | Main  |          |                         |
| comment:   |   |          |                         |
| Corrective Action                                      |   |          | Date:                   |
| Overall Good: <input checked="" type="checkbox"/>      |   |          |                         |
| <b>Signs/Marker:</b>                                   |   |          |                         |
| Type   | WELLHEAD  |          |                         |
| Comment:   |   |          |                         |
| Corrective Action:                                     |   |          | Date:                   |
| Emergency Contact Number:                              |   |          |                         |
| Comment:   | OK  |          |                         |
| Corrective Action:                                     |   |          | Date: _____             |
| Overall Good: <input checked="" type="checkbox"/>      |   |          |                         |
| <b>Spills:</b>   |   |          |                         |
| Type   | Area  | Volume   |                         |
| Lube Oil   | Pump Jack   | <= 1 bbl |                         |
| Comment:   | THIS SOILED DIRT NEEDS TO BE REMOVED INSTEAD OF POUTTING MORE DIRT ON THE STAINED SOIL  |          |                         |
| Corrective Action:                                     | "Comply with Rule 603.f using the Rule 603.f guidance document for further details. "   |          | Date: <u>12/02/2016</u> |
| Crude Oil  | Truck Loadout   | <= 1 bbl |                         |
| Comment:   | NEED CAP ON LOAD LINE   |          |                         |
| Corrective Action:                                     | "Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O."  |          | Date: <u>12/02/2016</u> |
| In Containment: No                                     |   |          |                         |
| Comment:   |   |          |                         |
| <input type="checkbox"/> Multiple Spills and Releases? |   |          |                         |
| <b>Fencing/:</b>                                       |   |          |                         |
| Type   | WELLHEAD  |          |                         |
| Comment:   | BARBWIRE FENCE  |          |                         |
| Corrective Action:                                     |   |          | Date:                   |
| <b>Equipment:</b>                                      |   |          |                         |
| Type: Pump Jack  | # 1   |          | corrective date         |
| Comment:   | PLATE ON MUFFLER THE BOLTS ARE STRIPPED NEEDS TO BE RETHREADED OR WELDED SHUT   |          |                         |
| Corrective Action:                                     | "Location is within a designated setback location, a leak detection plan is required. Fix the identified leak and then Implement the leak detection plan to ensure other leaks do not exist per Rule 604.c.(2)F." |          | Date: <u>12/02/2016</u> |
| <b>Venting:</b>  |   |          |                         |
| Yes/No   | NO  |          |                         |
| Comment:   |   |          |                         |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**Facility ID: 202912 Type: WELL API Number: 001-08317 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| <u>THE MUFFLER PLATE BOLTS ARE STRIPPED AND NEED TO BE REPAIRED AND STAINED SOIL CLEANED UP</u> | montoyaj | 11/18/2016 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                            | URL   |
|--------------|--|---|
| 685501392    | INSPECTION SUBMITTED                   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007180">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007180</a> |
| 685501393    | SOILED DIRT NEEDS REMOVED              | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007112">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007112</a> |
| 685501394    | BOLTS ARE STRIPPED WILL NOT HOLD PLATE | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007113">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007113</a> |
| 685501395    | WELL SITE                              | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007114">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007114</a> |
| 685501396    | NEED CAP ON LOAD LINE                  | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007115">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007115</a> |
| 685501397    | BATTERY SIGN                           | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007116">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007116</a> |