

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
11/28/2016  
Submitted Date:  
11/28/2016  
Document Number:  
674103857

**FIELD INSPECTION FORM**

Loc ID 332984 Inspector Name: Rickard, Jeff On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1775 SHERMAN STREET - STE 3000  
City: DENVER State: CO Zip: 80203

**Findings:**

16 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
General, All inspections	(970) 332-3520	cogccinspection@pdce.com	<a href="#">All PDC inspection</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243739	WELL	PR	11/30/2009	OW	123-11531	LEONARD & SON 1	PR
297438	WELL	PR	10/01/2009	OW	123-27133	VILLAGE 11-16DU	PR
297439	WELL	PR	10/01/2009	OW	123-27134	VILLAGE 22-16DU	PR
297440	WELL	PR	11/01/2009	OW	123-27135	VILLAGE 16A-DU	PR
297441	WELL	PR	10/01/2009	OW	123-27136	VILLAGE 16K-DU	PR
297442	WELL	PR	10/01/2009	OW	123-27137	VILLAGE 16F-DU	PR
297443	WELL	PR	10/01/2009	OW	123-27138	VILLAGE 16N-DU	PR

**General Comment:**

Inspected Facilities			
Facility ID:	243739	Type:	WELL
API Number:	123-11531	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	
<b>BradenHead</b>			
Comment:	Braden head is exposed at surface.		
Corrective Action:		Date:	
Facility ID:	297438	Type:	WELL
API Number:	123-27133	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	
<b>BradenHead</b>			
Comment:	Braden head is exposed at surface.		
Corrective Action:		Date:	
Facility ID:	297439	Type:	WELL
API Number:	123-27134	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	
<b>BradenHead</b>			
Comment:	Braden head is exposed at surface.		
Corrective Action:		Date:	
Facility ID:	297440	Type:	WELL
API Number:	123-27135	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	
<b>BradenHead</b>			
Comment:	Braden head is exposed at surface.		
Corrective Action:		Date:	
Facility ID:	297441	Type:	WELL
API Number:	123-27136	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 297442 Type: WELL API Number: 123-27137 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date: \_\_\_\_\_

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 297443 Type: WELL API Number: 123-27138 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date: \_\_\_\_\_

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action:

Date: \_\_\_\_\_

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input type="text"/> Corrective Action: <input type="text"/> Date: _____						
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

<b>COGCC Comments</b>		
Comment	User	Date
Location inventory has not changed since last inspection.	rickardj	11/28/2016