

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/16/2016

Submitted Date:

11/17/2016

Document Number:

674300783**FIELD INSPECTION FORM**
 Loc ID 311832 Inspector Name: Spencer, Stan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Dooling, Jessica	(970) 878-6800	Jessica_Dooling@xtoenergy.com	Piceance Basin Field
Lujan, Carlos		carlos.lujan@state.co.us	

**General Comment:**

**Environmental****Spills/Releases:**Type of Spill: CONDENSATEEstimated Spill Volume: -5100

Comment: Condensate spill from leaking manyway gasket on 210bbl AST within dirt secondary containment. Tank has been removed from metal rim base and placed on hypalon liner west of berm. Some soil has been removed from around tank base and is stockpiled within berm in 2cy supersacks. Staining around base may indicate that more excavation is needed.

Corrective Action: Complete assessment and remediation per COA of spill report approval.Date: 12/31/2016

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<u>Complete assessment and remediation per COA in F-19 approval.</u>	spencers	11/17/2016

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674300784	Tank base following removal	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014499">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014499</a>
674300785	leaking tank removed	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014500">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014500</a>
674300786	stockpiles soil	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014501">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014501</a>