

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
11/23/2016  
Submitted Date:  
11/29/2016  
Document Number:  
674300795

**FIELD INSPECTION FORM**

Loc ID 335383 Inspector Name: Spencer, Stan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 1 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Janicek, Jake		JJanicek@caerusoilandgas.com	
Lujan, Carlos		carlos.lujan@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**General Comment:**

*(This area is currently blank for general comments.)*

**Environmental**

**Spills/Releases:**

Type of Spill: CONDENSATE Estimated Spill Volume: \_\_\_\_\_

Comment: Site visit to assess Spill#448077 with Jake Janecek of Caerus. Condensate dumpline failed pressure test. Contaminated soil excavated to base of unstable cliff at north wall comprised of friable shale. ND for benzene and ~1000 ppm TPH in sample from cliff base but too dangerous for further excavation.

Corrective Action: Resample to assess natural attenuation. If TPH still exceeds Table 910-1 standard, consult with COGCC concerning other remedial options. Date: 12/30/2016

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674300796	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014774">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014774</a>