


API:	05-123-20962	ELEVATION:	4880	QTR-QTR:	NESW
WELL NAME:	Guest 11-13A	GROUND LEVEL:	4868	SECTION:	13
COUNTY:	WELD	MD:	7730	TOWNSHIP:	2N
LATITUDE:	40.13715	PBMD:	7702	RANGE:	65W
LONGITUDE:	-104.61558	CREATED BY:	E. HUNT		
		DATE:	11/29/2016		



COLOR KEY

GENERAL INPUTS	
Name	Elizabeth Hunt
Cell Phone Number	808-594-3092
Date	11/29/2016
WELL INPUTS	
Well Name	Guest 11-13A
API #	05-123-20962
WINS #	75408
Gyro Date:	Sept 2011
Surface Hole Size (in)	12.25
Prod Hole Size (in)	7.88
OH Excess Factor	60
Surface Casing (size/wt)	8-5/8", 24#
Surface Casing Shoe (ft)	942
Prod csg (size/wt)	4.5", 11.6#
Tubing OD (in)	2-3/8"
Tubing Set Depth (ft)	7530
Collar Above CIBP (ft)	7454
Collar Below CIBP (ft)	7496
Niobrara CIBP / BOC (ft)	7470
Niobrara TOC (ft)	6480
Niobrara Cement Vol (sx)	60
SUSX/SH BOC (ft)	4425
SUSX/SH TOC (ft)	4020
SUSX/SH Cement Vol (sx)	30
Bradenhead Issues? (Y/N)	N
Stub Plug BOC (ft)	1500
Cut Casing Depth (ft)	1400
Stub Plug TOC Form6 (ft)	892
Stub Plug TOC Calc (ft)	742
Stub Plug Cement Vol (sx)	220
GEOLOGY INPUTS	
FHM (ft)	1286
Sussex Top (ft)	4221
Sussex Base (ft)	4544
Shannon Base (ft)	Absent
Niobrara Top (ft)	6881
QUESTIONS?	
Who Drilled Well?	APC
Straight or Deviated Hole?	Straight
Age of well (yr)	14
Any squeeze holes? (Y/N)	N
Details of Integrity Issues?	DV Tool @ 4850'
SUSX/SH Productive? (Y/N)	N
Gyro Found (Y/N)	Y
CBL Found (Y/N)	Y
Packer Downhole? (Y/N)	N
Packer Depth (ft)	NA

*If No Integrity Issues, Put "NONE"

