



**photo 1:** Facing north along the access road.



**photo 2:** Facing west toward the location.





**photo 3:** Facing west along the north cut slope.



**photo 4:** Center of the location facing toward the north cut slope.





**photo 5:** Facing west along the south fill slope.



**photo 6:** Facing toward the southwest side of the location. There are signs of minor riling beginning to occur.