

Construction and Stormwater Inspection



Photo 1. Photo taken from the southeastern location, facing West, towards the sediment trap. Sediment trap does not have a stabilized outlet.

Construction and Stormwater Inspection



Photo 2. Photo taken from the eastern location, facing West, towards the topsoil stockpile. Topsoil has not been stabilized and protected from degradation due to wind and water erosion.

Construction and Stormwater Inspection



Photo 3. Photo taken from the northeastern location, facing West, towards the sediment trap. Sediment trap does not have a stabilized outlet.

Construction and Stormwater Inspection



Photo 4. Photo taken from the northern location, facing South, towards the sediment trap. Sediment trap does not have a stabilized outlet.

Construction and Stormwater Inspection



Photo 5. Photo taken from the north, western location , facing South. Stabilize the cut slope where soil was moved.

Construction and Stormwater Inspection



Photo 6. Photo taken from the south, western location , facing South. Stabilize the cut slope where soil was moved.