

Follow-up Inspection



Photo 1. Photo taken of wellhead sign. Sign is sufficient with the addition of the entrance sign- refer to Photo 3.

Follow-up Inspection



Photo 2. Photo taken of battery sign. Sign is sufficient with the addition of the entrance sign- refer to Photo 3.

Follow-up Inspection



Photo 3. Photo taken of sign at the entrance.

Follow-up Inspection



Photo 4. Photo taken of gravel placed around wellhead.

Follow-up Inspection



Photo 5. Photo taken at wellhead. It appears the impacted soil around the wellhead has not been removed. Removal of 3"-4" of gravel on top reveals stained soil with a hydrocarbon like odor.