



Photo 1. View of the beginning of the reclaimed access road facing southward.



Photo 2. View of the project area from the southwestern corner facing center. Revegetation is progressing with annual grasses and some perennial grasses such as smooth brome (*Bromus inermis*) and intermediate wheatgrass (*Thinopyron intermedium*)



Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 4. View of the western portion of the project area from the southwestern corner facing northward. Wattles appear to be in functioning condition.



Photo 5. View of the northern portion of the project area from the northeastern corner facing southward. Revegetation is progressing here.



Photo 6. View of rills in the northern portion of the project area. These need to be carefully monitored and stormwater BMPs applied if erosion worsens.



Photo 7. View of the eastern portion of the project area from the northeastern corner facing southward.



Photos 8-11. View of musk thistles (*Carduus nutans*) observed growing throughout the project area.