

Final Reclamation Inspection



Photo 1. Photo taken north of location, facing Southwest. Does not appear the well was constructed at the proposed location based off field observations.

Final Reclamation Inspection



Photo 2. Photo taken north of location, facing Southeast. Does not appear the well was constructed at the proposed location based off field observations.