



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward. Wood debris described in the August 2015 inspection has been removed.





Photo 3. View of the western portion of the project area from the southwestern corner facing northward.





Photo 4. View of area near well pad entrance where it appears stormwater erosion is repaired.