

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/29/2016

Submitted Date:

12/02/2016

Document Number:

682401584**FIELD INSPECTION FORM**

Loc ID 448368	Inspector Name: Binschus, Chris	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED								
Operator Information: OGCC Operator Number: <u>10311</u> Name of Operator: <u>SYNERGY RESOURCES CORPORATION</u> Address: <u>20203 HIGHWAY 60</u> City: <u>PLATTEVILLE</u> State: <u>CO</u> Zip: <u>80651</u>			Findings: 4 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested								
Contact Information: <table border="1" style="width:100%"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td></td> <td></td> <td>dpennington@syrinfo.com</td> <td></td> </tr> </table>				Contact Name	Phone	Email	Comment			dpennington@syrinfo.com	
Contact Name	Phone	Email	Comment								
		dpennington@syrinfo.com									

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448368	LOCATION	AC	11/18/2016		-	Orr State 40-36 Pad	CI

General Comment:
[This is a construction and stormwater inspection in response to Form 42 Document #401154212- Notice of construction of a new location.](#)

Location Construction

Location ID: 448368 CDP: _____

Comment: Topsoil has been salvaged and stored along the southern and western perimeter of location. Topsoil needs to be stabilized and protected from degradation due to wind and water erosion. BMPs to prevent weed establishment and to maintain soil microbial activity shall be implemented.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
DITCHES	Yes		

Comments: Erosion BMPs: _____

Other BMPs: _____

Corrective Action: _____ Date: _____

BERMS	Yes		
Comments: Erosion BMPs: <input type="text"/>			
Other BMPs: <input type="text"/>			
Corrective Action: _____			Date: _____

Comment: Culverts installed at location entrance to conjunction with borrow ditch and BMP (i.e., ditch and berm)

Corrective Action: **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____
 Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 448368 Type: LOCATION API Number: - Status: AC Insp. Status: CI**COGCC Comments**

Comment	User	Date
Follow up inspection(s) will proceed while construction of location is IN-PROCESS.	binschusc	12/02/2016
Refer to attached photos in Document #682401585.		

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401585	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017822