



photo 1: Facing northeast toward the location.



photo 2: Pipe risers remain near the location.



photo 3: The culvert near the access road is filled in with sediment.



photo 4: A sediment trap along the western side of the location is filled in with sediment.



photo 5: Facing northeast toward the cut slope of the location.



photo 6: Facing northeast toward the cut slope of the location.



photo 7: The lined pit remains at the east side of the location.



photo 8: Facing northwest. The lined pit remains at the east side of the location.



photo 9: Southeast side of the location facing northwest.



photo 10: Facing west along the south fill slope.



photo 11: Center of the location a conductor is present. Plastic safety fence is in disrepair.



photo 12: Southwest side of the location facing northeast.