

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/16/2016

Submitted Date:

11/17/2016

Document Number:

674300783**FIELD INSPECTION FORM**
 Loc ID 311832 Inspector Name: Spencer, Stan On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica	(970) 878-6800	Jessica_Dooling@xtoenergy.com	Piceance Basin Field
Fischer, Alex		alex.fischer@state.co.us	
Lujan, Carlos		carlos.lujan@state.co.us	

General Comment:

Environmental**Spills/Releases:**

Type of Spill: CONDENSATE

Estimated Spill Volume: -5100

Comment: Condensate spill from leaking manyway gasket on 210bbl AST within dirt secondary containment. Tank has been removed from metal rim base and placed on hypalon liner west of berm. Some soil has been removed from around tank base and is stockpiled within berm in 2cy supersacks. Staining around base may indicate that more excavation is needed.

Corrective Action: Complete assessment and remediation per COA of spill report approval.

Date: 12/31/2016

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
Complete assessment and remediation per COA in F-19 approval.	spencers	11/17/2016

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674300783	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014527
674300784	Tank base following removal	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014499
674300785	leaking tank removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014500
674300786	stockpiles soil	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014501