

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
11/22/2016  
Submitted Date:  
11/28/2016  
Document Number:  
674602961

**FIELD INSPECTION FORM**

Loc ID 319827 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10459  
Name of Operator: EXTRACTION OIL & GAS LLC  
Address: 370 17TH STREET SUITE 5300  
City: DENVER State: CO Zip: 80202

**Findings:**

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Hazard, Ellice		ellice.hazard@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Carlisle, Josh		jcarlisle@extractionog.com	
,		COGCCInspections@extracti onog.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201493	WELL	PR	04/30/2008	OW	001-06896	AYLOR 3	EG

**General Comment:**

COGCC Flowline Integrity Inspection performed on November 22nd, 2016 in response to initial form 19 spill report Doc #401152517 received on 11/18/2016 that outlines: During flowline pressure testing a leak was discovered. The details of the observations made during this field inspection are available in the flowline section of this report. Photo's have been uploaded and can be accessed via link(s) at the end of this report.

**Inspected Facilities**

Facility ID: 201493 Type: WELL API Number: 001-06896 Status: PR Insp. Status: EG

**Flowline**

#1	Type: Dump Line	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Dump Line Size: \_\_\_\_\_ Material: Carbon Steel  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: Multiphase

Integrity Summary

Failures: External Corrosion Spills: Yes Repairs Made: \_\_\_\_\_  
 Coatings: No H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: External corrosion holes (numerous) observed on the existing dump lines between the separator and production tanks. These lines are being removed and replaced. It is unclear at this time if the well site flowline, between the wellhead and separator, is scheduled for repair/ replacement. Note: Document and retain records of root cause of failure evaluation, preventative measures taken to prevent the problem from reoccurring and description of flowline repairs/ replacement(s) completed (on supplemental form 19) and perform flowline pressure testing (confirm integrity of all flowlines and repairs completed/ retain chart & data) prior to returning flowlines to service.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674602961	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4019184">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4019184</a>
674602972	Well Sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014358">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014358</a>
674602973	Excavation, remediation and repairs in progress	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014359">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014359</a>
674602974	External corrosion/ existing dump lines	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014360">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014360</a>