

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/16/2016

Submitted Date:

09/21/2016

Document Number:

674300772**FIELD INSPECTION FORM**
 Loc ID 334720 Inspector Name: Spencer, Stan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lujan, Carlos		carlos.lujan@state.co.us	
Inspection, Terra TEP	970-263-2716	COGCCInspectionReports@terraep.com	<a href="#">TEP Inspection Mail Box</a>
Burger, Craig		craig.burger@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**General Comment:**

**Environmental****Spills/Releases:**Type of Spill: DRILLING FLUIDS

Estimated Spill Volume: \_\_\_\_\_

Comment: Inspection SpillID 447807 9/16/16. Approximately 85 bbls of suspected drilling mud was discovered to have flowed to surface through the surface casing valve of the RWF414-4 well. The exact cause of why the mud came to surface is currently under investigation. A workover rig was set on the well on 9/15/16 to diagnose cause, and make repairs as needed. A vac truck was used to recover approximately 70 bbls of mud from the pad. The remaining 15 bbls flowed off location for a distance of approximately 80 yards. Mudflow was W/NW across grass pasture to edge of gully embankment. Sorbent boom placed at edge of flow. No visible flow over embankment to drainage. Impacted soil stockpile on pad and no staining or odor off location. Meet with Justin Skall, (TEP rep). Workover rig is setting plug to determine cause of leak.

Corrective Action: Assess nature and extent of contamination with confirmation soil samples. Remediate to Table 910-1 standards and provide documentation in a either a Supplemental F-19 if cleaned up immediately or F-27 if extended remediation is required. Manage all waste per COGCC 900 Rules. Provide any information that operator has available concerning wellbore integrity analysis, pressure testing, and any data concerning the root causes of the spill. Provide all engineering data to COGCC NW Engineering Supervisor, Dave Andrews at david.andrews@state.co.us and Craig Burger at craig.burger@state.co.us or 970-625-2497.

Date: 10/28/2016

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
674300772	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4019176">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4019176</a>
674300773	Looking S from end of mudflow	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014491">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014491</a>
674300774	Looking W, stockpiled soil and workover rig	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014492">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014492</a>