



photo 1: Facing east toward the location.



photo 2: There is List B noxious weeds (Diffuse knapweed) found growing throughout the location.



photo 3: East side of the location facing west.



photo 4: View of groundcover at the east side of the location. The vegetation has not adequately established in this area.



photo 5: Facing west along the fill slope.



photo 6: The fill slope is not adequately stabilized with vegetation and there are signs of erosion. The plastic netting debris remains.



photo 7: Northwest side of the location facing northeast toward the fill slope.



photo 8: There are signs of erosion along west side of the pad.